



Диаметры сверления отверстий для метчиков под метрическую резьбу

Все значения в таблице указаны в мм (миллиметрах)

Резьба	Шаг	Сверло	Резьба	Шаг	Резьба	Шаг	Резьба	Шаг	Резьба	Шаг	Резьба	Шаг
2	0.4	1.6	0.25	1.75								
3	0.5	2.5	0.35	2.65								
4	0.7	3.3	0.5	3.5								
5	0.8	4.2	0.5	4.5								
6	1	5	0.75	5.2	0.5	5.5						
7	1	6	0.75	6.2	0.5	6.5						
8	1.25	6.7	1	7	0.75	7.2	0.5	7.5				
9	1.25	7.7	1	8	0.75	7.2	0.5	8.5				
10	1.5	8.5	1.25	8.7	1	9	0.75	9.2	0.5	9.5		
11	1.5	9.5	1	10	0.75	10.2	0.5	10.5				
12	1.75	10.2	1.5	10.5	1.25	10.7	1	11	0.75	11.2	0.5	11.5
14	2	12	1.5	12.5	1.25	12.6	1	13	0.75	13.2	0.5	13.5
16	2	14	1.5	14.5	1	15	0.75	15.2	0.5	15.5		
18	2.5	15.4	2	16	1.5	16.5	1	17	0.75	17.2	0.5	17.5
20	2.5	17.4	2	18	1.5	18.5	1	19	0.75	19.2	0.5	19.5
22	2.5	19.4	2	20	1.5	20.5	1	21	0.75	21.2	0.5	21.5
24	3	20.8	2	22	1.5	22.5	1	23	0.75	23.2		
27	3	23.9	2	25	1.5	25.5	1	26	0.75	26.2		
30	3.5	26.4	3	26.9	2	28	1.5	28.5	1	29	0.75	29.2
33	3.5	29.4	3	29.9	2	31	1.5	31.5	1	32	0.75	32.2
36	4	31.9	3	32.9	2	34	1.5	34.5	1	35		
39	4	34.9	3	35.9	2	37	1.5	37.5	1	38		
42	4.5	37.4	4	37.9	3	38.9	2	39	1.5	40.5	1	41
45	4.5	40.4	4	40.9	3	41.9	2	43	1.5	43.5	1	44
48	5	42.8	4	43.9	3	44.9	2	46	1.5	46.5	1	47